

Technical revisions Airbag and belt tensioner Model 124

Type and reason for revision	Model	Launch/chassis no.	Op. no.
Use of a lighter-weight airbag unit with revised assembly procedure. Adjustment of diagonal play no longer included	124	Introduced approx. 11/85	91-660
Belt tensioner with approx. 80 mm shorter tube	124	Introduced approx. 08/87	91-600
New supplier for belt tensioner added, thus revised test after triggering	124	Introduced approx. 08/87	91-750
Relocated and revised adhesive label for replacement date of airbag unit	124	09/87	91-600
New control unit with integral voltage transformer and reserve power source with two triggering thresholds	124	09/87	91-600
Modified belt buckles with switches and resistors, thus belt tensioner triggered only when belt is worn	124	09/87	91-600
New control unit for service (3rd generation as of 09/87 adapted to 1st generation) Note on test coupling/plug connection for airbag, 10-pin Revised test for airbag 1/3	124	07/89	91-600